Sets, Kits, and Outfits, Components List, for Sheet Metal Working Outfit, Machine

SC: 4940-95-B01 NSN: 4940-00-273-4259 LIN: S94354 TM: 9-3445-102-14&P

System Description

Provides the necessary machine shop tools for a sheet metal worker's shop. Contains 30 components (folding, forming, brake, and shearing machines, soldering irons, file, carpenter's square, shears, melting pot, etc).

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
 • Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568) rock-pm-skot@conus.army.mil